

C E R T I F I C A T E

Management system as per
ISO 9001 : 2015

In accordance with TÜV NORD CERT procedures, it is hereby certified that

SILANG WATER DISTRICT
M.H. del Pilar cor. E. Montoya Sts. Brgy. I
4118 Silang, Cavite,
Philippines

applies a management system in line with the above standard for the following scope

Design of Pumping Station, Supply and Distribution of Water

Certificate Registration No. 44 100 17 93 0014

Audit Report No. SEATH-Q930155/2017

Valid from 2017-03-01

Valid until 2020-02-28

Initial Certification 2017-03-01



Certification Body
at TÜV NORD CERT GmbH

TÜV NORD (Thailand) Ltd.
1858/75-76 16th Floor, TCIF Tower,
Bangna-Trad Road, Bangna,
Bangna, Bangkok 10260, Thailand
2017-03-01

This certification was conducted in accordance with the TÜV NORD CERT auditing and certification procedures and is subject to regular surveillance audits.

TÜV NORD CERT GmbH

Langemarckstraße 20

45141 Essen

www.tuev-nord-cert.com

